

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, September 19, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County</b>	STA 14062+17 – 14171+36 STA 13575+00 – 13562+63	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:** Inspected the following resources: S-KL51, S-C8, S-KL41, S-KL61 and S-EF48.

STA 13575+00: Maintain CFS.

**Recommended Corrective Action:** Install and maintain all controls per the approved plans and PSS&S.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 09/19/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, September 19, 2019

Fig. 1: **STA 14170+00** – Controls in place. Area stabilized with seed and Earth Guard Edge.

☉ 256°W (T) ● 37°3'24"N, 79°50'46"W ±32.8ft ▲ 1026ft



Fig. 2: **Stream S-KL41** – Controls in place.

☉ 1°N (T) ● 37°3'44"N, 79°51'45"W ±32.8ft ▲ 1001ft



Fig. 3: **STA 14091+00** – Controls in place. Area stabilized with seed and Earth Guard Edge.

☉ 279°W (T) ● 37°3'50"N, 79°52'0"W ±16.4ft ▲ 1135ft



Fig. 4: **STA 13575+00** – CFS undermined.

☉ 191°S (T) ● 37°5'34"N, 79°58'48"W ±16.4ft ▲ 1313ft

