

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, September 2, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14050+00 – 14064+71 STA 14157+55 – 14175+00 STA 14233+12 – 14249+19 MVP-MLV-AR-32	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-YZ4, S-KL51, S-C19 and S-F11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, September 2, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 2, 2020

Figure 1: STA 14057+00 – Controls in place and functioning properly. Area stabilized with straw and erosion matting.

☉ 239°SW (T) ● 37°3'57"N, 79°52'37"W ±16ft ▲ 1197ft



14057

Figure 2: STA 14163+00 – Controls in place and functioning properly.

☉ 246°SW (T) ● 37°2'29"N, 79°51'13"W ±12405ft ▲ 1033ft



14163

Figure 3: STA 14172+00 – Controls in place and functioning properly. Area stabilized with straw.

☉ 40°NE (T) ● 37°3'26"N, 79°50'44"W ±16ft ▲ 1052ft



14172

Figure 4: Stream S-F11 – Controls in place and functioning properly around S-F11 crossing.

☉ 91°E (T) ● 37°3'11"N, 79°49'34"W ±32ft ▲ 853ft



S-F11