

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Stafford
<b>Inspection Date:</b>	Tuesday, July 3, 2018	<b>Project Contact:</b>	Brian Clauto
<b>Spread:</b>	Spread G	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                     
  Rough Grading                     
  Trench Excavation                     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                     
  Final Grading & Stabilization                     
  Other: \_\_\_\_\_

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

Area 1 - Jefferson National Forest station 11621+50 to 11661+25. (Approximate Mile Post (MP) 219.9 to 220.6) Work authorized in this area is limited to recovering woody debris (slash) placed outside the LOD and reestablishment of ESC measures. Re-inspection of established ESC measures is required prior to resumption of land disturbing activity. Contact DEQ for re-inspection.

Area 2 - Mt. Tabor Rd to Catawba Rd station 11789+02 To 12005+00 (Approximate MP 223.12 to 227.15) The ROW and two access roads (266.03 and 266) were inspected for compliance with required ESC measures and no deficiencies were observed.

**Deadline:**   N/A  

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  \_\_\_\_\_ Date: 7-16-18

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 3, 2018

Fig. 1  
Slash Pile on Brush Mountain (Area 1)



Fig. 2  
Area of work on Brush Mountain (Area 1)



Fig. 3  
Water Bar installation under pipe (Area 2)



Fig. 4  
Water Bar installation (Area 2)



Fig. 5  
Additional Karst Measures (Area 2)

