

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Stafford
Inspection Date:	Tuesday, July 10, 2018	Project Contact:	Brian Clauto
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:


Area 1 - Bonbrook Road to Angle Plantation Road, station 14019+00 (MP 265.4) to 14171+36 (MP 268.2). The ROW and one access road (MVP-FR-309) was inspected for compliance with required ESC measures and deficiencies were observed. Deficiencies included extension of bumpers at stream crossing, additional water bars and correction of one water bar cross-slope grade. All items were repaired prior to end of day inspection.

Area 2 – Angle Plantation Rd to Magoddee Creek, station 14171+36 (MP 268.2) to 14243+16 (MP 269.4). The ROW and one access road (FR-311) was inspected for compliance with required ESC measures and no deficiencies were observed.

Area 3 - Magoddee Creek to Blackwater River, station 14243+16 (MP 269.4) to 14249+19 (MP 269.8) . The ROW and one access road (MVP-MLV-AR32) was inspected for compliance with required ESC measures and no deficiencies were observed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-16-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 10, 2018

Fig. 1
Extended bumpers and install additional waterbar (Area 1)



Fig. 2
Clean water diversion (Area 1)



Fig. 3
Waterbar, typical (Area 1)



Fig. 4
ROW (Area 2)



Fig. 5
Waterbar, typical (Area 2)



Fig. 6

Fig. 7

Fig. 8