

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, October 9, 2018	Project Contact:	Brian Clauto
Spread: Franklin County MP 261 St#13819-13807	Spread I	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** –MP261 St#13819-13807 ECD's in place and stabilization has been applied. During the inspection construction was being conducted on the clean water pipe.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-5-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 9, 2018

<p>Fig. 1 At St#13819 stabilization has been applied.</p> <div style="text-align: center; background-color: #cccccc; padding: 5px;"> <p>South East Elevation</p> <p>📍 327°NW (T) ● 37°4'5"N, 79°55'20"W ±16.4ft ▲ 1101ft</p> </div> 	<p>Fig. 2 At St#13819 stabilization has been applied.</p> <div style="text-align: center; background-color: #cccccc; padding: 5px;"> <p>West Elevation</p> <p>📍 96°E (T) ● 37°4'5"N, 79°55'22"W ±16.4ft ▲ 1087ft</p> </div> 
<p>Fig. 3 At St#13817+10 clean water pipe install.</p> <div style="text-align: center; background-color: #cccccc; padding: 5px;"> <p>South East Elevation</p> <p>📍 307°NW (T) ● 37°4'6"N, 79°55'22"W ±16.4ft ▲ 1088ft</p> </div> 	