

# INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	John McCutcheon
<b>Inspection Date:</b>	Thursday, July 19, 2018	<b>Project Contact:</b>	Brian Clauto
<b>Spread:</b>	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- |  |  |  |  |
|--|--|--|--|
| <input type="checkbox"/> Clearing                          | <input checked="" type="checkbox"/> Rough Grading      | <input type="checkbox"/> Trench Excavation             | <input type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | <input type="checkbox"/> Other: <u>Stream Crossing</u> |  |

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: This report is for an inspection beginning at the end of Access Road MVP-Fr 291, STA 248.45 and ending at STA 13120+17 the vicinity of the Cahas Mountain Road 2 crossing from STA 13322+00 to STA 13346+00. (Note: These stations were taken off of the E&S plan sheets and differ from the stationing noted on the stakes in the field.)

1. Silt fence along ROW and at bottom of graded area OK.
2. Water bar at top of slope is poorly shaped with debris in flow line.
3. Water bar missing at STA 13119+00 between first and 2<sup>nd</sup> waterbars from top of slope
4. Water bars below 2<sup>nd</sup> waterbar unfinished/

**Deadline:** Within 24 hours of receipt or as noted

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 7-19-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 19, 2018

Comment 2.



Poorly shaped waterbar with debris in flowline.

Comment 3.



Waterbar missing on steep slope.

Comment 4.



Waterbar unfinished.

Comment 4.



Waterbar unfinished.