

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Stafford
Inspection Date:	Thursday, July 12, 2018	Project Contact:	Brian Clauto
Spread:	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

Area 1 - Dillion's Mill towards Blue Ridge Parkway, station 13117+50 (MP 248.4) to 13039+11 (MP 246.9) This area included a section of ROW and one access road (MVP-FR-291). ESC measures on the ROW were observed to be deficient. Contact to schedule for re-inspection prior to release.

Deficiencies included:

-Outstanding punch list items, additional stabilization necessary, water bars with height less than 18", and water bars needing additional compaction.

NOT RELEASED FOR WORK

Deadline: Prior to release for work

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-16-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, July 12, 2018

Fig. 1
Area above MVP-FR-291



Fig. 2
Water bar, good shape and compaction




Fig. 3
Water bar with no depth to hold water



Fig. 4
Downslope from water bars with no storage depth

