



VWP FIELD INSPECTION CHECKLIST

Short Form

Project Name	Mountain Valley Pipeline Spread I, Franklin County	VWP Permit #	N/A	Inspection Date	10/16/2018
Inspector Name	Nathan Hughes; Matt Grant	Phone # & Email Address	(804) 921-1970; Nathan.Hughes@deq.virginia.gov (804) 418-9874; Matthew.Grant@deq.virginia.gov		
Address or lat/long (if no permit no.)	Stream Crossing E-48 (BonBrook #2)	Others Present During Inspection	N/A		
Project Phase	Grading; Trenching	Reason for Inspection	Construction		
PERMIT / REGULATORY REQUIREMENT		Yes/ No/ NA	Location, Description and Other Notes		
Unauthorized impacts to surface waters, including wetlands, or upland preservation areas have occurred .* <i>(This includes sedimentation impacts due to inadequate or failed erosion controls.)</i>		Yes	Linear footage of stream channel impact unknown due to lack of adjacent landowner permission.		
Non-impacted wetlands, streams and preservation areas within 50 feet of construction are clearly marked to prevent unpermitted impacts.		Yes			
Temporary impacts are being restored to original contours, stabilized, and allowed to re-establish with wetland vegetation within 30 days of completing purposeful work in the area.		N/A			
Construction activities are not substantially disrupting aquatic life movement.		No	Sedimentation observed within stream channel's viable habitat		
E&S controls are present, properly maintained, and functioning.		Yes	At the time of inspection, E&S measures were being repaired		
In-stream work is being performed in the dry with the appropriate use of cofferdams, sheetpiling, etc., to minimize stream bottom disturbance and turbidity.		N/A			
Pipes and/or culverts for road crossings are countersunk to provide for the re-establishment of low flow fish passage and/or a natural stream bottom.		N/A			
Time-of-year restrictions are being adhered to.		N/A			
Water quality monitoring is being conducted during permanent stream relocations.		N/A			
Streams and wetlands are free from any sheen or discoloration that may indicate a spill of oil, lubricants, concrete or other pollutants. **		Yes			

Heavy equipment is placed on mats or geotextile fabric when working in authorized temporary wetland impact areas.	N/A	
Exposed slopes/stream banks are stabilized immediately upon completion of work in each impact area.	N/A	

Inspection Summary

Compensation Completed	Reporting	On-Site Monthly Inspections Completed
<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	Preconstruction Notice Received: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Construction Status Updates Received: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A

Notes

General Notes:

On October 16, 2018, DEQ staff conducting field inspections documented sedimentation in Stream E-48 located on property adjacent to and within the Mountain Valley Pipeline (MVP) right-of-way (RoW).

Construction Activities at time of Inspection:

Stormwater measures and Erosion & Sediment Controls

Stream E-48

Sediment ranging from <0.5-inch to a maximum depth of 2-inches was observed. Sediment was also observed within forested buffer. Flow was present in the 1-3' wide channel at time of inspection. Sediment within the stream's thalweg was generally <1-inch in depth; sediment bars and pool deposition was generally 1 to 2-inches in depth. Landowner permission was not granted for adjacent property downstream.

Clean-up activities and seed/straw present at time of inspection, however more remediation needed

Recommended Corrective Actions

1. Repair erosion and sediment controls in areas where needed;
2. Stabilize all slopes above and below perimeter controls;
3. Remove sediment from impacted stream channel using hand removal methods (buckets and shovels) and stabilize with appropriate seed mix where applicable.

Site Inspection

Site Name: Mountain Valley Pipeline_Spread I; Stream E-48

Date: 10/16/2018



Photo 1: Overview of Stream Crossing E-48

Orientation: ENE



Photo 2: View downstream from bridge in Photo 1

Orientation: Downstream

Site Inspection

Site Name: Mountain Valley Pipeline_Spread I; Stream E-48

Date: 10/16/2018



Photo 3: Sediment in stream and on banks at edge of RoW; Depth = 0.5-2"
Orientation: Downstream

Site Inspection

Site Name: Mountain Valley Pipeline_Spread I; Stream E-48

Date: 10/16/2018



Photo 4: Overview of stream crossing and sediment within forested buffer
Orientation: SE