FIELD INSPECTION

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Matthew Grant**
Inspection Date:	**Tuesday, August 28, 2018**	**Project Contact:**	**Brian Clauto**
Spread:	**Spread I**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☐ Clearing ☒ Rough Grading ☐ Trench Excavation ☐ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration ☒ Final Grading & Stabilization ☐ Other: _____

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments:

- **Area 1** - Spread I, Franklin County, near Cahas Mountain Road, approximately MP 254 permanent water bars were being installed.
- **Area 2**- Spread I, Franklin County, near Grassy Hill Rd, approximately MP 259.40 temporary stabilization had been applied and maintenance had been conducted on conveyance channels.
- **Area 3**- Spread I, Franklin County, near Iron Ridge Rd, approximately MP 262.90 temporary stabilization had been applied.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ___ Date: ____9-17-18_____

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Tuesday, August 28, 2018**

Fig. 1
Near MP 262 temporary stabilization had been applied.

Fig. 2
Near MP 259 temporary stabilization has been applied.

Fig. 3
Near MP 259 rock conveyance channels had been maintained.

Fig. 4
Near MP 254 permanent waterbars were being installed