FIELD INSPECTION

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Matthew Grant**
Inspection Date:	**Wednesday, August 14, 2019**	**Project Contact:**	**Brian Clauto**
Spread: Montgomery Co. MP228-230 St12070-12190 AR275 ATWS 1375	**Spread H**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☐ Clearing ☐ Rough Grading ☐ Trench Excavation ☐ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☒ Other: Dormant

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☐	☒	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments:

- Inspected designated streams included: SC-21, ECD's were in place at designated stream crossing and functioning.
- St12188+00 stockpile lacks stabilization.
- St12190+00 sump lacks adequate storage

Recommend Corrective Action: Maintain and install all controls per the approved plan and specs

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:___ ___ Date: _8-19-19

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Wednesday, August 14, 2019**

- Fig. 1 St12188+00 stockpile lacks stabilization

- Fig. 2 St12190+00 sump lacks adequate storage

- Fig. 3 Designated stream SC-21, ECD's are in place and functioning.

- Fig. 4 ATWS1375 is stabilized and ECD's are in place and functioning