Temperanceville
Outfall 001 Discharge Point
Tyson Farms Temperanceville Facility
Image © 2008 Commonwealth of Virginia
© 2008 Tele Atlas
Google
Imagery Date: Feb 1, 2007
37°53'17.87" N 75°33'21.08" W elev 12 m
Eye alt 1.70 km