FIELD INSPECTION

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Matthew Grant**
Inspection Date:	**Thursday, January 10, 2019**	**Project Contact:**	**Brian Clauto**
Spread: Montgomery County MP228-231	**Spread H**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☐ Clearing ☐ Rough Grading ☐ Trench Excavation ☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☒ Other: dormant

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☐	☒	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments:

- MP 229 St#12132+91 CFS is torn and bridge crossing near designated stream SC-29
- MP 231 St#12235+92 area has been stabilized.
- MP 228 St#12072+84 area has been stabilized.
- MP 230 St#12152+00 area has been stabilized
- ECD are in place and functioning at designated streams SMM-11, SMM-13, SF-16

Recommended Corrective Action: Maintain all controls per the approved plan and annual standards and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:___ ___ Date: 2-12-19

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Thursday, January 10, 2019**

- Fig. 1 CFS at st#12132+91 is torn at bridge crossing

- Fig. 2 Desginated stream SC-29 controls in place and functioning

- Fig. 3 Aquatic resource at ST#12132+00 repairs have been made and controls in place and functioning.

- Fig. 4 Aquatic resource at ST#12132+00 repairs have been made and controls in place and functioning.

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Thursday, January 10, 2019**

- Fig. 5 MP 228 St#12072+84 area has been stabilized

- Fig. 6 ECD are in place and functioning at designated stream SMM-13

- Fig. 7 ECD are in place and functioning at designated stream SF-16

- Fig. 8 MP230 St#12152+00 area has been stabilized