FIELD INSPECTION

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Matthew Grant**
Inspection Date:	**Tuesday, February 5, 2019**	**Project Contact:**	**Brian Clauto**
Spread: Franklin County MP 262-264	**Spread I**	**Weather (Wet/Dry/Rain):**	**Dry**

STAGE OF CONSTRUCTION: (Check all that apply)

☐ Clearing ☐ Rough Grading ☐ Trench Excavation ☒ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☒ Other: Dormant

		Yes	No	N/A
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☐	☒	☐
3	Areas of offsite sediment deposition were observed?	☐	☒	☐

Comments:

- Streams / wetlands inspected included W-CD1, S-CD1, S-II2, C-17, W-CD6, CD6.
- St#13955+05 P1 fence requires maintenance
- St#13919+00 sump inlet requires maintenance
- ATWS 698C P1 fence and CFS requires maintenance
- St#13909+08 slope requires repair and stabilization
- St#13906+077 waterbar exceeds 5%
- St#13899+92 sump end treatment requires maintenance
- St#13897 sump requires maintenance
- St#13869+00 area lacks stabilization near staged pipe and CWD
- St#13877+00 P1 fence and CFS requires maintenance, trash beyond ROW.
- St#13875+73 CFS requires maintenance

Recommended Corrective Action: Maintain all controls per the approved plan and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ___ Date: 2-12-19

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Tuesday, February 5, 2019**

- Fig. 1 St#13955+05 P1 fence requires maintenance

- Fig. 2 St#13919+00 sump inlet requires maintenance



- Fig. 3 ATWS 698C P1 fence and CFS requires maintenance

- Fig. 4 St#13909+08 slope requires repair and stabilization



FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Tuesday, February 5, 2019**

- Fig. 5 St#13906+077 waterbar exceeds 5%

- Fig. 6 St#13899+92 sump end treatment requires maintenance

- Fig. 7 St#13897 sump requires maintenance

- Fig. 8 St#13875+73 CFS requires maintenance

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:Tuesday, February 5, 2019**

- Fig. 9 St#13869+00 area lacks stabilization near staged pipe and CWD

- Fig. 10 St#13877+00 P1 fence and CFS requires maintenance, trash beyond ROW.