# FIELD INSPECTION REPORT

| | | | |
|---|---|---|---|
| **Project Name:** | **Mountain Valley Pipeline** | **Inspector:** | **Marshall Willis** |
| **Inspection Date:** | **Monday, June 22, 2020** | **Project Contact:** | **Brian Clauto, Cory Chalmers** |
| **Spread I:**<br>**Pittsylvania County** | **STA 15743+00 – 15826+77**<br>**ATWS 500/794/504/399** | **Weather:** | **Dry** |

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

☐ Tree Felling ☐ Clearing/Grubbing ☐ Grading ☐ Trenching ☐ Stringing/Welding

☐ Lowering/Backfilling ☐ Final Restoration ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Dormant

| | | Yes | No | N/A |
|---|---|---|---|---|
| *1.* | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| *2.* | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| *3.* | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

*Comments:* Inspected the following resources: S-DD4, S-KL27 and S-C1.

**Recommended Corrective Action**: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date**: **Monday, June 22, 2020**

# FIELD INSPECTION PHOTO LOG

**Project Name:** **Mountain Valley Pipeline** **Date:** **Monday, June 22, 2020**

Figure 1: **STA 15826+00** – Controls in place and functioning properly. Area stabilized.

Figure 2: **Stream S-C1** – Controls in place and functioning properly around stream crossing.

Figure 3: **STA 15765+00** – Controls in place and functioning properly. Area stabilized.

Figure 4: **STA 15756+50** – Controls in place and functioning properly. Area stabilized.