DEQ
VIRGINIA DEPARTMENT OF
ENVIRONMENTAL QUALITY

# FIELD INSPECTION

| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
|---|---|---|---|
| Inspection Date: | Wednesday, September 26, 2018 | Project Contact: | Brian Clauto |
| Spread: Montgomery County | Spread H | Weather (Wet/Dry/Rain): | Wet |

**STAGE OF CONSTRUCTION:** (Check all that apply)

☐ Clearing ☐ Rough Grading ☒ Trench Excavation ☒ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☒ Other: Stream crossing

|   |   | Yes | No | N/A |
|---|---|---|---|---|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☒ | ☐ | ☐ |

Comments:
- **Area 1** – Follow up to inspection on 9/25/18, MP 227.9 station#12035+19 designated stream SG-40 additional controls below dewatering structure were installed, pump around rock outfall energy dissipater was installed. Remove sediment per DEQ approval.

**Deadline:** within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:___ _(signature)_ ___ Date: __11-5-18_____

# FIELD INSPECTION PHOTO LOG

**Project Name:**   <u>Mountain Valley Pipeline</u>                    **Date:Wednesday, September 26, 2018**

Fig. 1
MP 227.9 St#12035+19 designated stream SG-40 dewatering structure outfall area



Fig. 2
MP 227.9 St#12035+19 designated stream SG-40 dewatering structure outfall area



Fig. 3
Designated stream SG-40 pump around energy dissipater



Fig.4
Sediment in stream