

Archived: Thursday, June 30, 2016 11:43:04 AM
From: Glassman, Joseph (DEQ)
Sent: Thursday, June 30, 2016 11:41:00 AM
To: 'Jason P Ericson (Services - 6)'
Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarolo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)
Subject: RE: Crystal Substation and Roaches Run Weekly Update: June 27, 2016
Importance: Normal

Jason,

DEQ has no objection to reducing the inspection frequency to once per week. Randy checked with the other members of the unified command and there were no objections.

Joe Glassman
Environmental Specialist
Virginia Department of Environmental Quality
Northern Regional Office
13901 Crown Court
Woodbridge, VA 22193
703-583-3808
joseph.glassman@deq.virginia.gov
www.deq.virginia.gov

From: Jason P Ericson (Services - 6) [mailto:jason.p.ericson@dom.com]
Sent: Monday, June 27, 2016 12:12 PM
To: Glassman, Joseph (DEQ)
Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarolo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)
Subject: Crystal Substation and Roaches Run Weekly Update: June 27, 2016

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point. The insertion of dye was completed on June 16th. We have sample collection packets in the storm sewer system and the Roaches Run outfalls. Observations indicate that there is not continued contribution of oil or sheen from the Crystal Substation into Roaches Run or the Gravelly Point Area. As a result of these observations, we request that the inspection frequency be reduced to once per week with the last daily inspection occurring on Thursday, June 30th.

If you have any questions please contact John Black or me.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: June 27, 2016**

Summary Monday June 20 – Friday June 24: No sheen was observed at any of the locations inspected this week. Dye testing was initiated on Thursday June 16. No dye was noted at any of the locations during our inspections Monday through Friday of this week (June 20-24). A greenish hue was observed at Outfall #2 during inspections on June 18 (Saturday) and June 19th (Sunday) but the coloration was not observed after June 19th. We will be analyzing the sample packets which will allow us to determine if the color is associated with the dye test and if so, the path the dye took to Roaches Run.

Below you will find our daily observations for inspections:

Monday 10:00 pm June 20 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of sheen. Roaches Run parking area showed no signs of oil or sheen. No dye noted at any of the areas.

Tuesday 10:30 pm June 21 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of sheen. Roaches Run parking area showed no signs of oil or sheen. No dye noted at any of the areas.

Wednesday 10:00 am June 22 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of sheen. Roaches Run parking area showed no signs of oil or sheen. No dye noted at any of the areas.

Thursday 11:34 pm June 23 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Absorbent boom was changed as a precaution. Gravelly Point boat launch area showed no signs of sheen. Roaches Run parking area showed no signs of oil or sheen. No dye noted at any of the areas.

Friday 12:00 pm June 24 (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of sheen. Roaches Run parking area showed no signs of oil or sheen. No dye noted at any of the areas.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.