

**Archived:** Wednesday, July 13, 2016 9:52:37 AM  
**From:** Glassman, Joseph (DEQ)  
**Sent:** Tuesday, July 12, 2016 8:16:00 AM  
**To:** 'Jason P Ericson (Services - 6)'  
**Cc:** Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6); Erica L Stratton (Services - 6)  
**Subject:** RE: Crystal Substation and Roaches Run Weekly Update: July 11, 2016  
**Importance:** Normal

---

Jason,

As we discussed yesterday, Randy will be checking with the other members of the Unified Command to see if there are any objections to removing the booms. Also, I am planning to be in the area on Thursday for the drilling and I will take a look at the booms at that time. After my inspection we will make a decision on your request to remove the booms.

Joe Glassman  
Environmental Specialist  
Virginia Department of Environmental Quality  
Northern Regional Office  
13901 Crown Court  
Woodbridge, VA 22193  
703-583-3808  
[joseph.glassman@deq.virginia.gov](mailto:joseph.glassman@deq.virginia.gov)  
[www.deq.virginia.gov](http://www.deq.virginia.gov)

---

**From:** Jason P Ericson (Services - 6) [mailto:jason.p.ericson@dom.com]  
**Sent:** Monday, July 11, 2016 9:52 PM  
**To:** Glassman, Joseph (DEQ)  
**Cc:** Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6); Erica L Stratton (Services - 6)  
**Subject:** Crystal Substation and Roaches Run Weekly Update: July 11, 2016

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point. We are now conducting inspections once per week. We are currently maintaining boom in the vicinity of Outfall #2 into Roaches Run. We have not observed oil or sheen at this outfall in recent inspections and request approval to permanently remove the remaining boom.

If you have any questions please contact John Black or me.

**Crystal Substation Daily  
Inspection Notes: July 11, 2016**

**Thursday 10:00 am; July 7 (high tide)** – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of oil. Absorbent boom was changed as a precaution. Gravelly Point boat launch area showed no amounts of sheen. Roaches Run parking area showed no signs of sheen. No dye was noted at any of the inspection areas.

Thank you,  
Jason

Jason P. Ericson, PG  
Dominion Resources Services, Inc.  
Environmental Policy  
5000 Dominion Blvd  
Glen Allen, VA 23060  
Phone: (804) 273-3012  
Mobile: (804) 317-9464  
Fax: (804) 273-2964

---

**CONFIDENTIALITY NOTICE:** This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.