

Archived: Tuesday, May 17, 2016 11:44:21 AM

From: Jason P Ericson (Services - 6)

Sent: Monday, May 16, 2016 2:30:14 PM

To: Glassman, Joseph (DEQ)

Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)

Subject: Crystal Substation and Roaches Run Weekly Update: May 16, 2016

Importance: Normal

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point.

If you have any questions please contact John Black or me.

Thank you,

Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: May 16, 2016**

Summary Monday May 9 – Friday May 13: A slight sheen and debris were observed in the area of the Roaches Run outfall following rain events. No sheen or oil was observed at any of our inspection areas at any of the other inspections during the week. No accumulations of oil or sheen were observed in vaults inside or outside the Station. The dye tracer study at the Crystal Substation originally planned for the week of May 2nd, has been moved to the week of May 30th.

Below you will find our daily observations for inspections:

Monday May 9, 9:00 am (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. Vaults are collecting rain water.

Tuesday May 10, 8:00 am (low tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Wednesday May 11, 10:30 am (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Thursday May 12, 8:45 am (low tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. Booms replaced at outfall #2 as a precaution.

Friday May 13, 9:30 am (low tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run outfall showed very slight sheen and debris along bank. Roaches Run parking area showed no signs of oil or sheen. Gravelly Point boat launch area showed no signs of oil or sheen. Vaults and containments pumped of rainwater. Approximately 2900 gallons shipped for disposal.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.