

Archived: Tuesday, April 26, 2016 8:20:35 AM

From: Jason P Ericson (Services - 6)

Sent: Monday, April 25, 2016 7:44:49 PM

To: Glassman, Joseph (DEQ)

Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)

Subject: Crystal Substation and Roaches Run Weekly Update: April 25, 2016

Importance: Normal

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point.

If you have any questions please contact John Black or me.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: April 25, 2016**

Summary Monday April 18 – Friday April 22: A slight sheen was noted on one day at the Gravelly Point boat launch area. No accumulations of water or oil in vaults inside or outside the Station were observed. It should also be noted that Carbon packs were installed at various inspection locations and storm water drop inlets in preparation of dye testing

Below you will find our daily observations for inspections:

Monday, April 18, 3:00 pm (low tide) – The storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen or sheen. All vaults are empty. Note: While doing the inspection today it was observed that a construction crew working at apartment complex next to the train station had a skid steer release hydraulic fluid onto pavers behind the apartment complex with a drop inlet nearby. This drop inlet goes to Outfall Area 1.

Tuesday, April 19, 7:45 am (high tide) – The storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil or sheen. The Gravelly Point boat launch area showed a small amount of sheen at the boat ramp, docks and edge of water. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty.

Wednesday, April 20, 7:30 am (high tide) – The storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil or sheen. Gravelly Point boat launch showed no oil or sheen at the boat ramp or dock area. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty.

Thursday, April 21, 10:00 am (high tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil, and absorbent boom was changed as a precaution. Gravelly Point boat launch area showed no amounts of sheen. Roaches Run parking area showed no signs of oil and sheen. All vaults are empty.

Friday, April 22, 10:30 am (high tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil or sheen. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.