

Archived: Monday, April 11, 2016 12:41:56 PM

From: Jason P Ericson (Services - 6)

Sent: Friday, April 08, 2016 1:11:56 PM

To: Glassman, Joseph (DEQ)

Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6)

Subject: Crystal Substation and Roaches Run Weekly Update: April 8, 2016

Importance: Normal

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point. We have not observed any oil or sheen at any of the inspection locations for the second week in a row. Accordingly, we request reducing the inspections to daily during the week and no inspections on the weekend. Please let us know if reducing the inspection frequency is acceptable.

If you have any questions please contact John Black or me.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: April 8, 2016**

Summary Friday April 1 - Thursday April 7: No oil of any kind has been seen at any of the inspection points for the second week in a row. Additionally, no accumulations of water or oil in vaults inside or outside station were observed this week. All vaults that have been previously inspected were power washed this week by HEPACO.

Below you will find our daily observations for inspections:

Friday 11:00 pm April 1 (low tide) – Storm water drop inlet outside Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Saturday 8:10 am April 2 (high tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Sunday 8:00 am April 3 (high tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen.

Monday 1:00 am April 4 (very low tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty and no pumping was required.

Tuesday 1:30 am April 5 (very low tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty and no pumping was required. Pumped total of 250 gallons rain water from all 4 liners in substation.

Wednesday 11:30 am April 6 – Due to staff involvement in construction activity occurring at the Crystal Substation, inspections were not conducted.

Thursday 9:00 am April 7 (high tide) – Storm water drop inlet outside station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no amounts of sheen. Roaches Run parking area showed no signs of sheen. All vaults are empty and no pumping was required. HEPACO initiated power washing of the vaults.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.