

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Tuesday, September 17, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery County AR256 MP215-217 Giles County MP218-218.2</b>	Spread G	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant/ winter stabilization

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Inspected designated streams included: SKL-43,S-OO14, S-OO13, S-OO12, S-PP1, S-PP3
- ECD's inspected were in place at designated stream crossings.
- St11520+00 sump requires maintenance

**Recommend Corrective Action:** Maintain and install all controls per the approved plan and specs

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 10-9-19

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, September 17, 2019

- Fig. 1 St 11520+00 sump requires maintenance



- Fig. 2 Near ST11354+00 area has been stabilized with seed and mulch



- Fig. 3 Near MP 216.3 holes protected per DCR Will Orndorff.



- Fig. 4 Near St11524 stabilization has been applied by helicopter near the base Sinking Creek Mountain.

