

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, July 31, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread H: Montgomery County</b>	STA 12445+19 – 12482+67 MVP-MLV-AR-28	<b>Weather (Wet/Dry/Rain):</b>	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other:

- |   |   | Yes                      | No                                  | N/A                      |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CD12b and W-KL58.

STA 12479+75 to 12480+00: SSF undermined.  
 STA 12480+00: SSF cleanout required.  
 STA 12480+00: Replace damaged bridge wattle.  
 STA 12481+00: Replace damaged bridge wattle.  
 STA 12482+00: SSF undermined.  
 STA 12482+00: CFS maintenance required.  
 STA 12483+00: Sump maintenance required.  
 STA 12483+00: Waterbar failure.  
 STA 12482+95: No end-treatment at end of waterbar, sump maintenance needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and specs.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 07/31/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, July 31, 2019

Fig. 1: **STA 12479+75 to 12480+00** – SSF undermined.



Fig. 2: **STA 12480+00** – SSF maintenance required.



Fig. 3: **STA 12480+00** – Replace damaged bridge wattle.



Fig. 4: **STA 12481+00** – Replace damaged bridge wattle.



# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, July 31, 2019

Fig. 5: **STA 12482+00** – SSF undermined.



Fig. 6: **STA 12482+00** – CFS maintenance needed.



Fig. 7: **STA 12483+00** – Sump maintenance needed.



Fig. 8: **STA 12483+00** – Waterbar repair needed.



# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, July 31, 2019

Fig. 9: **STA 12483+95** – No end-treatment. Sump maintenance needed.

