

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, February 27, 2019	Project Contact:	Brian Clauto
Spread: Roanoke County AR 288	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|--------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Access Road 288 erosion controls were in place and functioning.
- Inspected designated stream and wetlands included: S-Q20, W-Q11, W-IJ10, and W-Q10

Recommended Corrective Action: Remove roadside gravel in wetland if owner permission is obtained.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 3-4-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 27, 2019

- Fig. 1. Wetland W-IJ10 controls were in place and functioning at the time of inspection. Roadside gravel has impacted wetland as noted in previous inspections.



- Fig. 2. At designated stream S-Q20 at the time of the inspection no road side gravel was in stream.



- Fig. 3. At AR 288 erosion controls were in place and functioning at the time of the inspection.

