

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, October 23, 2019	Project Contact:	Brian Clauto
Spread: Franklin Co. AR FR306.02 MP264.9-265.1 ATWS 1466 MP263.1-263.4 MP259.4-258.9 ATWS 1067 MP258.2 MP254.3 AR FR 293.02 ATWS1343 & 1342 MP261.7-261.4 AR FR302 ATWS 346	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams and wetlands included: S-KL36, S-II, S-E28, W-E7, W-E8, S-E29
- ECD's inspected were in place at designated crossings.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-15-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 23, 2019

- Fig. 1. At designated stream S-KL36, ECD's are in place and area has been stabilized.



- Fig. 2 At designated stream S-II2, ECD's are in place and functioning.



- Fig. 3 At designated stream S-E29, ECD's are in place and functioning.



- Fig. 4 Near St13820+00 slope is stabilized.

