

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, May 14, 2019	Project Contact:	Brian Clauto
Spread: Pittsylvania County MP296-298 St15650-15739	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams / wetlands inspected included: S-Q4, W-Q2, S-Q3, S-Q2, SB-6, SB-8, SB-9. ECD's were in place at all inspected streams and no impacts were observed.
- St#15699- Soil stockpile lacks adequate stabilization
- Designated stream SB-8 remove accumulated sediment from bridge approach and repair undermined CFS

Recommended Corrective Action: Maintain all controls per the approved plan and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.


Inspector Signature: Matthew Grant Date: 6-17-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, May 14, 2019

▪ Fig. 1 St15699 soil stock pile lacks adequate stabilization



▪ Fig. 2 SB-8 remove accumulated sediment from bridge approach and repair undermined CFS

