

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, June 19, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County Pittsylvania County	STA 14928+52 – 14981+55 STA 15112+57 – 15143+00	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G15, S-G13, S-A11 and S-A6.

- STA 14932+28: CFS maintenance needed.
- STA 14938+00: CFS maintenance needed.
- STA 14943+00: CFS maintenance needed. Repair/stabilize perimeter berm.
- STA 14944+00: CFS maintenance needed. Repair/stabilize perimeter berm.
- STA 14947+00: CFS maintenance needed.
- STA 14951+00: Sediment off ROW.
- STA 14951+00 through 14953+50: CFS maintenance needed.
- STA 14967+00: CFS maintenance needed.
- STA 14974+00: Sediment off ROW.
- STA 14974+50: CFS maintenance needed.
- STA 15126+00: CFS maintenance needed.
- STA 15126+00: P1 maintenance needed.
- STA 15143+00: CFS maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 06/19/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 19, 2019

Fig. 1: STA 14932+28 – CFS maintenance needed.



Fig. 2: STA 14938+00 – CFS maintenance needed.



Fig. 3: STA 14943+00 – CFS maintenance needed. Repair and stabilize diversion berm.



Fig. 4: STA 14944+00 – CFS maintenance needed. Repair and stabilize diversion berm.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 19, 2019

Fig. 5: STA 14947+00 – CFS maintenance needed.



Fig. 6: STA 14951+00 – Sediment off ROW.



Fig. 7: STA 14951+00 to 14953+50 – CFS maintenance needed.



Fig. 8: STA 14967+00 – CFS maintenance needed.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 19, 2019

Fig. 9: STA 14974+00 – Sediment off ROW.



Fig. 10: STA 14974+50 – CFS maintenance needed.



Fig. 11: STA 15126+00 – CFS/P1 maintenance needed.



Fig. 12: STA 15143+00 – CFS maintenance needed.

