

FIELD INSPECTION

| | | | |
|---|--------------------------|--------------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Wednesday, July 10, 2019 | Project Contact: | Brian Clauto |
| Spread: Franklin County MP266-265 St14061+00-14043 | Spread I | Weather (Wet/Dry/Rain): | Dry |

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams / wetlands inspected included: S-YZ4, S-YZ5.
- Streams S-YZ4 and S-YZ5 had been impacted by sediment and noted on the 7-9-19 report. MVP environmental crews were on site working on repairs per the inspection conducted on 7-9-19, multiple issues were noted including sediment off the ROW, stabilization and ECD maintenance.
- Area of sediment off ROW had been removed and area was stabilized at the time of the 7-10-19 inspection

Recommended Corrective Action: Maintain controls per the approved plan and annual standard and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 7/22/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 10, 2019

- Fig. 1 Stabilization issue had been noted for St14061 through 14043 on the 7-9-19 report.



- Fig. 2 Designated stream S-YZ4 during the inspection MVP crews were on site conducting repairs to the ECD's.



- Fig. 3 Designated stream S-YZ 5, controls had been repaired per the 7-9-19 report.



- Fig. 4 Near St14045+71 Sediment off ROW has been removed and the area stabilized.

