

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, July 18, 2018	Project Contact:	Brian Clauto
Spread: Locations in Spread I inspected included MP 273.56-273.95, MP 277.26-278, MP 259.4 -259.56	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: _____

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

Area 1 - Spread I, near MP 273 at station 14461+02 culvert pipe is not protected

Recommended Corrective Action: protect culvert inlet pipe

Area 2 - Spread I, near MP 277 at station 14649+00 culvert pipe under construction entrance lacks outlet protection and conveyance channel below pipe lacks stabilization.

Recommended Corrective Action: protect outlet and stabilize conveyance channel

Area 3 - Spread I, near MP 259.4 to MP 259.3 conveyance channels below water bars has escaped sediment in channel.

Recommended Corrective Action: Clean conveyance channel and stabilize associated areas near channel

Area 4 - Spread I, near MP 254.4 to MP 254.5 areas where the pipe has been trenched and backfilled lacks stabilization.

Recommended Corrective Action: Stabilize areas where backfilling has occurred and completed

Deadline: Within 24hrs of notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-23-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 18, 2018

Fig. 1 near station 14461+02 culvert inlet pipe



Fig. 2 near station 1469+00 culvert pipe outlet and conveyance channel



Fig. 3 near MP 259.4 rock conveyance channel



Fig. 4 backfilling of trench is ongoing near MP 254.5

