

Facilities Permitted to Accept Friable Asbestos (RACM*)

Blue Ridge Region

First Piedmont Industrial Landfill, SWP065 1224 Clarks Mill Rd, Ringgold Pittsylvania County	(434) 432-0211 (800) 476-6780	Privately owned; No area restriction. Can also deliver bins for collection and transport See website
Smith Gap Regional Landfill, SWP555 RVRA, Roanoke County	540) 857-5820	From service area only: City of Roanoke, County of Roanoke, Town of Vinton See procedures

Piedmont Region

King and Queen County SLF, SWP554 1000 Iris Road, Little Plymouth	(804) 785-2146	Non-hazardous friable and non-friable See website
Maplewood Recycling & Waste Disposal, 20221 Maplewood Road, Jetersville Amelia County, SWP 540	(804) 561-5787	Non-hazardous friable and non-friable WMSolutions
Old Dominion SLF, SWP553 2001 Charles City Road, Richmond	(804) 226-6197	Non-hazardous friable and non-friable

****Regulated asbestos-containing waste material generated in a demolition or renovation operation shall be disposed in a special purpose landfill or in a designated area of a sanitary landfill (9VAC20-81-620.C.1). A sanitary landfill that is not permitted to accept friable asbestos may request to accept it as a special waste.***