

INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Wednesday, July 11, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

This report covers observations made along a continuous section of the ROW beginning at Blackwater River Crossing 2 (STA 14270+00, MP 269.8) to State Route 40 (STA 14649+67, MP 277.3).

STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | |
|--|--|--|--|
| <input type="checkbox"/> Clearing | <input checked="" type="checkbox"/> Rough Grading | <input type="checkbox"/> Trench Excavation | <input type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | <input type="checkbox"/> Other: _____ | |

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Entire length of this section cleared. Grading completed from start at Blackwater River, MP 269.8 to STA 272.0.
- Water bars from Blackwater River, MP 269.8 to Farm View Drive, MP 270.9 not acceptably shaped and flow lines in channel were not continuous or clear. Water bars were shaped and compacted and flow lines cleaned before day's end.
- Length of Rock Construction Entrance at Golden View Road STA 14454+27, MP 274.9 was short. Additional stone was installed and Entrance was at specified length before day's end.
- Access roads also reviewed within this section include:
 - MVP-FR 318
 - MVP-FR 319.01

Deadline: _____ N/A _____

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: John R. McCutcheon Date: 7-11-18