

INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Tuesday, July 10, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

This report covers observations made along a continuous section of the ROW beginning at Cahas Mountain Road Crossing 2 (STA 13415+38, MP 253.9) to US Route 220 (STA 13930+00, MP 265.15).

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Pipe installed and backfilled in short sections between STA 13415+38, MP 253.9 and 13496+14, MP 255.4.
- 75 ft. length of side slope at STA 13496+14 was recently graded and required stabilization. Stabilization provided before day's end.
- Upper part of slope around recently graded work area at MP 261 off Access Road MVP-FR 300 required stabilization. Stabilization provided before day's end.
- Sections of water bars located under strung pipe between MP 262.2 and 262.4 were not continuous or not compacted. Sections of pipe were lifted out of the way and the water bars were connected, shaped and compacted before day's end.
- Access roads also reviewed within this section include:
 - MVP-FR 293.02
 - MVP-FR 295.01
 - MVP-FR 300
 - MVP-FR 302
 - MVP-FR 305

Deadline: _____ N/A _____

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 7-10-18