

## COMPLAINT INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	John McCutcheon
<b>Inspection Date:</b>	Thursday, August 9, 2018	<b>Project Contact:</b>	Brian Clauto, Tim Bowen
<b>Spread:</b>	Spread G	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                     
  Rough Grading                     
  Trench Excavation                     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                     
  Final Grading & Stabilization                     
  Other: \_\_\_\_\_

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: This report is for an inspection at an area Giles County, east of Doe Creek Farm and south and west of Mountain Lake Road at about MP 207.75, in response to a complaint of sediment-laden water running off the ROW and into streams at stream crossings S-E24 and S-E25.

1. E&S controls appeared in good condition.
2. Stabilization applied to streambank next to timber bridge at S-E25.
3. Stream channels appeared in good condition. Sediment deposits not evident and water in channels flowing clear.

**Deadline:**   N/A  

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: John R. McCutcheon

Date:   8-9-18

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 9, 2018

Comment 1.



E&S controls in good condition.

Comment 2.



Stabilization applied to streambank.

Comment 3



Sediment deposits not evident in channel. Water flowing clear.

Comment 4.