

COMPLAINT INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Tuesday, August 14, 2018	Project Contact:	Brian Clauto, Tim Bowen
Spread:	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: This report is for an inspection at an area Giles at Old Furnace Road and Sinking Creek, in response to a complaint of sediment-laden water running off the ROW and stream.

1. E&S controls appeared in good condition.
2. Sinking Creek water appeared flowing clear with no apparent sediment deposits.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: John R. McCutcheon

Date: 8-14-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 14, 2018

Comment 1.



E&S controls in good condition.

Comment 1.



E&S controls in good condition.

Comment 2.



Sinking Creek water at stream crossing S-KL43 appeared flowing clear with no apparent sediment deposits.