

## **Field Inspection Report**

		<u> </u>				_		
Project Name:	Mountain Valley Pipeline	Inspector:	Inspector:				Matthew Grant	
Inspection Date:	Tuesday, January 7, 2020	Project Co	ect Contact:			Br	Brian Clauto	
Spread: Giles Co. AR GI 256.02	Spread G	Weather (V	ther (Wet/Dry/Rain):			w	et	
STAGE OF CONSTRUCTI  Clearing  Backfilling and Grade	Rough Grading  Restoration  Final Grading		on	No	N/A		Pipe Assembly, Testing & Installation Other: <u>Dormant</u>	
Are controls installed and implemented in accordance with the approverosion and sediment control plan and stormwater management plan								
Are all control meas condition in accorda applicable, manufac		$\boxtimes$						
3 Areas of offsite sedi	ment deposition were observed?							
<ul><li>ECD's controls wer</li><li>Due to snow and po</li></ul>	ed stream included: S-NN11 e in place and functioning at crossing por road conditions, a portion of AR-C		as no	ot ad	ccessil	ole fo	r inspection.	

## **Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Date: 2-3-2020



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Tuesday, January 7, 2020

-	Fig. 1 Designated stream crossing S-NN11 ECD's in place and functioning.	
	place and functioning.	
	· ·	
	North Elevation	
	The second secon	