

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, October 29, 2019	Project Contact:	Brian Clauto
Spread: Montgomery Co. ATWS 1487 MLV 26 ATWS 1057 MN 258.04 ATWS 1373 MP223.1 MP222.7 MP219.5	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing
 Rough Grading
 Trench Excavation
 Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration
 Final Grading & Stabilization
 Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams and wetlands included: WI-J46-PFU, SI-J52, S-RR13, S-RR14, S-006
- ECD's were in place and functioning at the designated crossings.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-15-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 29, 2019

- Fig. 1 ATWS 1487 has been stabilized and ECD's are in place and functioning.



- Fig. 2 Designated stream S-IJ 52, ECD's in place and functioning.



- Fig. 3 Designated stream S-RR14, ECD's are in place and functioning.



- Fig. 4 ATWS 1057 & designated stream S-RR13 ECD's are in place and functioning.

