

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, February 26, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MN 266 MP 225 11932+54 MP226 11979+30	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | |
|--|--|--|--|
| <input type="checkbox"/> Clearing | <input type="checkbox"/> Rough Grading | <input type="checkbox"/> Trench Excavation | <input type="checkbox"/> Pipe Assembly, Testing & Installation |
| <input type="checkbox"/> Backfilling and Grade Restoration | <input type="checkbox"/> Final Grading & Stabilization | | <input checked="" type="checkbox"/> Other: Dormant |

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Access Rd MN 266 controls were in place and functioning at the time of the inspection.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Date: 3-4-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 26, 2019

- Fig. 1 St#11934+71 near the top of Catawba Mtn. controls were in place and functioning, area has been stabilized.



- Fig. 2 St#11979+30 near the base of Catawba Mtn. controls were in place and functioning, area has been stabilized



- Fig. 3 St#11979+30 near the Karst feature at the base of Catawba Mtn.

