

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, February 28, 2019	Project Contact:	Brian Clauto
Spread: Giles County AR GI-234 AR GI-249.01 MP 211.6 ST#11172+48--+70 AR GI-249.02 ST#11184+00-11193+85 Craig County MP218 ST#11530+00-11529+50 MP216 ST#11487+00	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Access Rd GI-234 Rodgers Road, ECD's in place and functioning.
- Access Rd GI-249.01 ECD's in place and functioning.
- Access Rd GI-249.02 ECD's in place and functioning
- At St#11529+50 slope has slipped and lacks stabilization.

Recommended Corrective Action: Maintain all controls per the approved plan.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 3-4-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 28, 2019

Fig. 1 Access Road GI-234, controls in place.



Fig. 2 ST#11184+00 plunge pool area has been repaired



Fig. 3 At St#11529+50 slope has slipped and lacks stabilization.



Fig. 4 At St#11172+48 P1 control has been repaired.

