

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, March 12, 2019	Project Contact:	Brian Clauto
Spread: Giles County MP214 St#11330-11322 Montgomery County MP221-222 11670-11743	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Streams / wetlands inspected included: S-MN21, S-MN22, S-EF65, S-NN12, GH7, S-GH15, S-GH14
- St#11675+30 P1 fence is undermined
- St#11677+50 sump triple stack is undermined
- St#11679+40 sump triple stack is undermined
- St#11686+81 SS fence is undermined
- .

Recommended Corrective Action: Maintain all controls per the approved plan.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 3-21-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 12, 2019

Fig. 1 St#11675+30 P1 fence is undermined



Fig. 2 St#11677+50 sump triple stack is undermined



Fig. 3 St#11679+40 sump triple stack is undermined



Fig. 4 St#11686+81 SS fence is undermined

