



# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 18, 2019

Fig. 1: **S-RR14** – Controls in place.



Fig. 2: **STA 11619+00** – Area adequately stabilized. Controls in place.



Fig. 3: **STA 11606+00** – Area adequately stabilized. Controls in place.



Fig. 4: **S-006** – Controls in place.





# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 18, 2019

Fig. 5: **STA 11526+00** – Area adequately stabilized. Controls in place.



Fig. 6: **STA 11522+00** – Area adequately stabilized. Controls in place.



Fig. 7: **STA 11507+00** – Area adequately stabilized. Controls in place.



Fig. 8: **STA 11501+11** – Area adequately stabilized. Controls in place.

