FIELD INSPECTION REPORT

Project Name:	**Mountain Valley Pipeline**	**Inspector:**	**Marshall Willis**
Inspection Date:	**Wednesday, May 13, 2020**	**Project Contact:**	**Brian Clauto, Cory Chalmers**
Spread G: **Montgomery County**	**STA 11765+50 – 11800+00** **STA 11601+00 – 11620+00** **MVP-MLV-AR-26** **MVP-MN-258.04**	**Weather:**	**Dry**

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

☐ Tree Felling ☐ Clearing/Grubbing ☐ Grading ☐ Trenching ☐ Stringing/Welding

☐ Lowering/Backfilling ☐ Final Restoration ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Dormant

		Yes	No	N/A
1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3.	Areas of offsite sediment deposition observed?	☐	☒	☐

Comments: Inspected the following resources: S-IJ52, W-IJ46-PEM, S-OO6, S-RR13 and S-RR14.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Wednesday, May 13, 2020**

FIELD INSPECTION PHOTO LOG

Project Name: **Mountain Valley Pipeline** **Date:** **Wednesday, May 13, 2020**

Figure 1: **STA 11784+00** – Controls in place and functioning properly. Area stabilized with straw.

Figure 2: **STA 11792+00** – Controls in place and functioning properly.

Figure 3: **Stream S-RR13** – Controls in place and functioning properly along S-RR13.

Figure 4: **STA 11608+40** – Controls in place and functioning properly along Craig Creek.