

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 2, 2019	Project Contact:	Brian Clauto
Spread G: Giles County	STA 10929+62 – 11151+27	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E24, S-E25, S-RR5, S-IJ18 and S-IJ16b.

- STA 10985+50 – Stabilize bank on CIS of S-E24.
- STA 11046+00 to 11049+00 – Install end treatments per PSS&S.
- STA 11119+00 – Clean out sump, install end treatment per PSS&S.
- STA 11120+00 – Repair waterbar.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/02/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 2, 2019

Fig. 1: STA 10941+00 – Controls in place. Area stabilized.



Fig. 2: STA 10973+00 – Controls in place. Area stabilized.



Fig. 3: STA 10985+50 – Stabilize erosion CIS stream S-E24.



Fig. 4: STA 11021+00 – Controls in place. Area stabilized.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 2, 2019

Fig. 5: STA 11046+00 to 11049+00 – End treatments not installed per PSS&S.



Fig. 6: STA 11119+00 – Sump maintenance needed. End treatment not installed per PSS&S.



Fig. 7: STA 11120+00 – Waterbar maintenance needed.



Fig. 8: STA 11127+00 – Controls in place. Area stabilized.

