

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, July 30, 2019	Project Contact:	Cory Chalmers
Spread: Giles County MP215 AR GI256 St11354-11385 Montgomery Co. MP223-225 St11788-11900	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Designated stream inspected included: SKL-43, S-NN12, S-NN13. ECD controls were in place and functioning at crossings.
- Stabilization completed from St11354+00 through 11385+00 at the time of inspection, remaining stabilization required to 11472. Stabilization issue was noted for corrective action on 7-17-19, with a current deadline date of 8-8-19. MVP staff was on site during the inspection conducting stabilization methods.
- Sediment was being removed off the ROW at St117833, at the time of the inspection.

Recommended Corrective Action: Maintain all controls per the approved plan and specs, remove escaped sediment per DEQ approval.

Deadline: 8-8-19

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-30-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 30, 2019

Fig. 1. Sediment was being removed at the time of the inspection at St 117833.



Fig. 2. Final stabilization efforts at St117818.



Fig. 3. Final stabilization efforts at St117838.



Fig. 4. Stabilization applied at St11354

