

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, August 1, 2019	Project Contact:	Cory Chalmers
Spread: Giles County AR 249.01 MP211-212 St11191-11227 MP215-217 St11354-11472	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Designated stream inspected included: SKL-43, S-0014, S-0013, S-0012. ECD controls were in place and functioning at crossing.
- Stabilization completed from St11354+00 through 11415+00 at the time of inspection, remaining stabilization required from St11415-11472. Stabilization issue was noted for corrective action on 7-17-19, with a current deadline date of 8-8-19. MVP staff was on site during the inspection conducting stabilization methods.

Recommended Corrective Action: Maintain all controls per the approved plan and specs

Deadline: 8-8-19

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-5-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 1, 2019

Fig. 1. St11354+00 areas has been seeded and mulched.



Fig. 2. Holes noted by Will Orndorff of DCR remain protected near MP 216.3



Fig. 3. Holes noted by Will Orndorff of DCR remain protected near MP 216.3



Fig. 4. Designated streams S-0012 and S-0013 no impacts were observed.

