

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, August 29, 2018	Project Contact:	Brian Clauto
Spread:	Spread G	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: _____


- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- **Area 1** - Spread G, Giles County, near Rogers Rd, access Rd G-I234 rock lined channel had been worked on and stockpile had been stabilized.
- **Area 2**- Spread I, Giles County, near Old Furnace Rd, approximately MP 214 temporary stabilization was being applied.
- **Area 3**- Spread I, Giles County, near Sinking Creek Mtn, approximately MP 218 station #11528+40 the water bar observed required maintenance.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 9-17-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 29, 2018

Fig. 1
Near Access Rd G-I234 rock lined channel was being installed.



Fig. 2
Near Access Rd G-I234 stockpile had been stabilized.



Fig. 3
Near MP 218 ST# 11529+40 water bar required maintenance



Fig. 4
Near MP 214 stabilization was being applied by helicopter.

