# FIELD INSPECTION

| | | | |
|---|---|---|---|
| **Project Name:** | **Mountain Valley Pipeline** | **Inspector:** | **Matthew Grant** |
| **Inspection Date:** | **Thursday, September 13, 2018** | **Project Contact:** | **Brian Clauto** |
| **Spread: Montgomery County** | **Spread G** | **Weather (Wet/Dry/Rain):** | **Wet** |

**STAGE OF CONSTRUCTION:** (Check all that apply)

☐ Clearing ☐ Rough Grading ☐ Trench Excavation ☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilization ☒ Other: Storm preparation

| | | Yes | No | N/A |
|---|---|---|---|---|
| *1* | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| *2* | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| *3* | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- **Area 1** – In the area of MP 226 station # 11934+00 – 11950+00 karsts areas protected
- **Area 2**- MP 223.22 station # 11786+41 karsts area protected

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: ___ Date: 9-17-18

# FIELD INSPECTION PHOTO LOG

**Project Name:** **Mountain Valley Pipeline** **Date:Thursday, September 13, 2018**

Fig. 1
MP 226.17 karsts feature protected

Fig. 2
MP 226.02 karsts feature protected

Fig. 3
MP 226.37 karsts feature protected

Fig. 4
MP 226.42 karsts feature protected