

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, October 17, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 12690+43 – 12710+00 MVP-RO-288/291.01 STA 12634+42 – 12643+70	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- Clearing Rough Grading Trench Excavation Pipe Assembly, Testing & Installation
 Backfilling and Grade Restoration Final Grading & Stabilization Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following ATWS: 955, 955A, 968 and 1329.

Recommended Corrective Action: N/A.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 10/17/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 17, 2019

Fig. 1: **STA 12691+04** – Controls in place. Area stabilized with Proganics soil media and hydraulic mulch.



Fig. 2: **STA 12643+70** – Controls in place. Area stabilized with Proganics soil media and hydraulic mulch.



Fig. 3: **STA 12703+08** – Controls in place. Area stabilized with Proganics soil media and hydraulic mulch.



Fig. 4: **MVP-RO-288** – Controls in place. Area stabilized with Proganics soil media and hydraulic mulch.

