

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, October 8, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Montgomery County</b>	STA 12101+57 – 12200+00	<b>Weather (Wet/Dry/Rain):</b>	Rainy

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Winterization/Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-OO11, S-C21, S-C24, S-C25, S-C29, S-MM31, S-C36, S-F15 and S-MM11.

**Recommended Corrective Action:** N/A.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 10/08/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, October 8, 2019

Fig. 1: **STA 12190+00** – Controls in place in place at Bradshaw Road.



Fig. 2: **STA 12200+00** – Controls in place. Area stabilized with hydraulic mulch and straw.



Fig. 3: **STA 12117+62** – Controls in place. Area stabilized with straw and erosion matting.



Fig. 4: **Stream S-MM11** – Controls in place. Area stabilized with straw and erosion matting.

