

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 19, 2018


- Fig. 1 St#12038+00 plunge pool installed and functioning.



- Fig. 2 designated stream crossing S-G36 controls in place and functioning.



- Fig. 3 St#10273+65 matting has been installed and is functioning.



- Fig. 4 St#12031+56 at designated stream S-G 39 controls in place and functioning.

