

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Thursday, December 19, 2019	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Franklin County</b>	STA 12994+00 – 13042+58 STA 13251+29 – 13267+40 STA 13316+13 – 13295+82	<b>Weather (Wet/Dry/Rain):</b>	Wet

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                       Rough Grading                       Trench Excavation                       Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                       Final Grading & Stabilization                       Other: Dormant

- |   |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G24, W-ST2-PEM, S-H1, S-II4 and S-GH7.

**Recommended Corrective Action:** N/A

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/19/2019

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, December 19, 2019

Fig. 1: **STA 12996+61** – Controls in place and properly functioning at the Blue Ridge Parkway.



Fig. 2: **STA 13260+00** – Controls in place and functioning properly. Area stabilized.



Fig. 3: **Stream S-GH7** – Controls in place and functioning at Stream S-GH7.



Fig. 4: **STA 13306+16** – Controls in place and properly functioning. Area stabilized.

