

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Wednesday, December 4, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery Co.</b> AR MN 278.01 ATWS 645 ATWS 1225 ATWS 1224 Roanoke Co. MP240.2-240 MP239.2 AR-RO 279.01	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- Clearing                     
  Rough Grading                     
  Trench Excavation                     
  Pipe Assembly, Testing & Installation  
 Backfilling and Grade Restoration                     
  Final Grading & Stabilization                     
  Other: Dormant

- |   | Yes                                 | No                                  | N/A                      |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- Inspected designated streams and wetlands included: S-EF19, W-CD11, W-CD11UP
- ECD's were in place and functioning at the designated crossings.
- During the inspection ECD maintenance was being conducted.

**Recommend Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 12-16-19

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, December 4, 2019

- Fig. 1. Near MP 237.5 stockpiles have been stabilized.



- Fig. 2. Near MP 237.2 slope drains are functioning and ECD maintenance is being conducted.



- Fig. 3. Near MP 237.3 ECD maintenance was being conducted.



- Fig. 4. Above designated stream S-EF19, ECD's are in place and functioning.

